



Figure 10-15. Photograph of a disturbed vibratory core. Note that the thin horizontal layers of dark sediment are curved downward due to sampling disturbance. (Figure provided by the U.S. Naval Facilities Engineering Service Center)